

NEBRASKA DEPARTMENT OF AERONAUTICS

Dave Heineman
Governor

Stuart MacTaggart
Director

Mr. John Troxel, Chairman
Sargent Airport Authority
P.O. Box 134
Sargent, NE 68874

November 7, 2008

Subject: Sargent Municipal Airport
Sargent, Nebraska
Pavement Condition Index (PCI) Survey

Dear Mr. Troxel:

This Department last conducted a survey of the operational area pavement conditions for your airport in 2008. We are in the process of renovating our entire PCI process and have encountered some delays in our reporting. We are sorry for the delay, but finally here are the results of the 2008 survey.

Enclosed is a report containing information on the inspection results and an estimate of the maintenance needs at your airport. The report is based on the inspector's visual observations, and should not be used as the basis of actual construction or repairs without the consultation and advice of a registered Professional Engineer.

- Overall, the airport pavement was in excellent condition.

Please feel free to contact this office if you have any questions in regard to the enclosed report, or if you would like to request state assistance for any needed repairs.

We will be inspecting your airport again in 2011 and our report should follow within a couple months of the inspection.

Sincerely,

NEBRASKA DEPARTMENT OF AERONAUTICS


Bob Richter
Engineering Division

Enclosures

Main Office

Mailing Address
P.O. Box 82088
Lincoln, Nebraska 68501
402.471.2371
402.471.2906 fax

Office Location

3431 Aviation Road Suite 150
Lincoln, Nebraska 68524

www.aero.state.ne.us

Navigational Aids Office

Kearney Municipal Airport
5065 Airport Road
Kearney, Nebraska 68847
308.865.5696
fax 308.865.5697

Date: 11 /7/2008

Section Condition Report

1 of 2

Pavement Database: NetworkID: 09K

Branch ID	Section ID	Last Const. Date	Surface	Use	Rank	Lanes	True Area (SqFt)	Last Inspection Date	Age At Inspection	PCI
SARA1 (APRON IN FRONT OF T-HANGA)	01	06/04/1999	AC	APRON	P		2,944.00	07/30/2008	9	100.00
SARR1 (RUNWAY 17/35)	01	06/04/1999	AC	RUNWAY	P		150,000.00	07/30/2008	9	97.00
SART1 (CONNECTING TAXIWAY)	01	06/04/1999	AC	TAXIWAY	P		15,625.00	07/30/2008	9	97.00

Date: 11 /7/2008

Section Condition Report

2 of 2

Pavement Database:

Age Category	Average Age At Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI
06-10	9.00	168,569.00	3	98.00	1.41	97.05
All	9.00	168,569.00	3	98.00	1.41	97.05